



Vermont Department of Public Safety  
**DIVISION OF FIRE SAFETY**  
 Office of the State Fire Marshal, State Fire Academy and State Haz-Mat Team  
 firesafety.vermont.gov



Waterbury Regional Office  
 45 State Drive  
 Waterbury, VT 05671-8200  
 [phone] 802-479-4434  
 [fax] 802-479-4446

Rutland Regional Office  
 56 Howe Street, Building A, Suite 200  
 Rutland, VT 05701-3449  
 [phone] 802-786-5867  
 [fax] 802-786-5872

Williston Regional Office  
 380 Hurricane Lane, Suite 101  
 Williston, VT 05495-2080  
 [phone] 802-879-2300  
 [fax] 802-879-2312

Springfield Regional Office  
 100 Mineral Street, Suite 307  
 Springfield, VT 05156-3168  
 [phone] 802-216-0500  
 [fax] 802-216-0511

**FIRE INSPECTION RESULTS**

Site Id: 17151

**Structure Information**

Name: GREENSBORO TOWN HALL & CLASSROOMS Address: 81 LAURENDON AVENUE  
 Structure Id: 17151 GREENSBORO, VT 05841

**Business Owner**

Name: TOWN OF GREENSBORO (N 25010) Address: PO BOX 119  
 eMail: townclerk@greensborovt.org GREENSBORO, VT 05841  
 Phone: 802-533-2911

**Building Description**

Risk Index: M2	Smoke Det: No	Occupants: 100	Units:
Const Type: 4B	CO Detect: No	Stand Pipe:	Floors: 2
Occ Type: A3E	Fire Alarm: Automatic	Sprinkler: Limited	Sq Feet:
Heating: Oil Hot Air			

**Project Description**

Name: INSPECTION  
 Type: Building Project Received: 07/17/2024 Workitem Id: 506073

**Inspection Detail**

Insp Date: 07/17/2024	Insp Type: Initial	Violations:
Comply By:	Occ Granted: Yes	Hazard Index: Level 2
Inspector: Shawn M Goodell (S 111869)		
With: Chantelle & Becky - Rural Edge		

**Violations and Notes**

Site Visit/ Inspection

This report contains violations in its current occupancy.

Violations:

- 1) Electrical shall be gone through by an electrician as there are many electrical violations.
- 2) Emergency/Exit lights shall be inspected and all working properly.
- 3) Mechanical room has a 1 hour rating. There are open penetrations that shall be filled in and the rated door is coming apart and does not self close.
- 4) Rated doors throughout the building have been modified with door stoppers and a locking mechanism at the top. Rated doors shall not be modified unless specifically allowed by the manufacturer.

\*\*\*For proposed use a code analysis shall be done by an architect\*\*\*